ODOT/AGC

1200-CA Permit update first since 2000



In my allotted time today, I can't train to the full content of the Permit. Contractors their, ESCMs need to read the Permit

1200-CA Permit update will require changes to Erosion and Sediment Control Plan implementation and compliance with permit requirements during construction – Changes are a large leap



Permit Documents are located in the ODOT Erosion & Sediment Control web page under Guidance Materials ESCP during construction – READ THE PERMIT

Permit Update Timeline

Projects will be held to the updated Permit's requirements on **April 1, 2023** Except

Permit Section 16 – Corrective Actions are now in effect. This is of critical importance to DEQ



Redefine ESCP

Erosion and Sediment Control Plan is not just the plan sheets, but a folder of information including:

- ESC Plan Sheets Revised prior to construction and several times during Construction
- Landscape Plan Sheets if they provide final stabilization
- Erosion and Sediment Control narrative
- 00280 Specifications AND Special Provisions
- 00290 Specifications AND Special Provisions
- 01030 Special Provisions
- Standard Drawings used on a Project
- Monitoring reports
- ESCP revisions
- Corrective Action self reports, and Plan submittals

DEQ requires the ESCP to provide an understanding of all aspects of Project that affects erosion & sediment control and pollution prevention


Contractor Must Revise ESCP Prior to Beginning Construction to Provide the following:

- Contractors working on Project site,
- Personnel's name & position for all staff designing, installing & maintaining ESC during construction,
- Staging area, stockpile area, materials processing area with appropriate ESC BMPs
- Location(s) of above items if not on ODOT land
- Personnel conducting monitoring (ESCM) including name, title, contact information & certification Environmental Management Plan if applicable
- Have CURRENT copy of ESCP on site. Electronic file is OK

ODOT submits ESCP with required Cover Sheet to DEQ prior to bid let and Contractor must revise, prior to construction, with personnel & Project info that was not available during design

ΙГ						MOTES	The paralities is required to meet all the conditions of the 1260-CN paralit. This SCP and general conditions have been developed to facilitate compilarity with 1200-CN paralit supercade requirements of this plan.										
Ш					The construction, adjustment, and appreciage of						PMP MATRIX FOR CONSTRUCTION PHASES						
ш	1 '1			l I	Address	alon and rediment control revariants is the response for the description of the resident to come	patrol measures is the responsibility	Befor to DEQ Guidance Hannal for a comprehensive for of markship SMP's									
ш					Fur: 503 Section			contractor for the chrusien of the project to comply with 100280 of the Oruges Standard Specifications for	Phone 1 Phone 7 Phone 3 Phone 45740 Tra								
ш							marine	ten and the 1910ES 1200-CA person.		GLEP Alterno				X X			
ш							Broadon &	nd Sedhwent Control measures shown on this ;	alien atre			_	-	-	-		
ш							for analog	erd Sodieront Control mouseurs shown on this ; parted site conditions. Adjust or approach these for anaugueted states amount to ansure that a numb-ladar mater does not have the arts.									
ш	l					rent-fester vester does not have the artis.	***************************************			_	_	_	_				
ш								e realised plan of the Broaton and Sediment Con-				-	-	_	_		
ш								e obsesse are assessment for Especial CASSIN Plantage				\neg					
ш							Standard	Specifications for Construction, implement this distribution and in segment									
SITE MAP				NARRATIVE DESCRIPTIONS		mentile and d	o to mach standno edunas. Chantroet in such a so				\rightarrow	-	_	_			
				District of Soft Applications		20 40 (0.4	nsare that sediment and sediment Index nates the readeny or dislange system, or violets up,	dour			-	-	_	_			
ш			TO SCALE		3111		nerter size	ran rosamy ar arawaye system, ar vicala ap nalande	ne nee			-	-	_	_		
IL			roution Only			state areas, and driveways											
I							Status and Otherwise	rasares mithén tón right-of-nny anims director L	,								
							-					+	+	_	+		
П	1 1			- + T			573,604	NO DILANGUE				-	-	_	+		
П	1 1					1906 - Chartraction Stomacer											
П				I I			_ no	1965 Chack Davis Type 1, 2 and 4									
П								1006 Check Dame Type 2 and 6				-	_		+		
П								1910 - Inlet Protection Type 2, 3, 6, 7 10 and 1915 - Inlet Protection Type 4	77			+	+	_	+		
П	I						- A	1973 Great Printerson 1996 1 1080 Sectionary Service Time 2, 3 and 4				-	-		+		
П							0 20	1980 Sediment Border Type 2, 3 and 4 1981 Sediment Border Type 5 and 5									
ш					□ RD1032 Sediment flurille Tipa d												
			#201085 Sediment Spring 5														
										Symbles arithment BBP's required for more within 50° or super of the state. Symbles also these all to installed prior to any ground distribution partiesy. BATCHMAE ETATEMENT A comparison list of modulule hour management practices (IMP) options have 120°; gettings stated first beautiful prior to the 120°; gettings stated and replace carried plant, 500 and the stated field? we not chance became felar party.							
WICHTIY MAP				R01089 The Wash Facility Type I and 2 R01089 Submissed Trap Rout Des Submissed Trap Rout													
For Inflavoution Only									SHEET INDEX			control peak, some or me move amon some very not causes aneather observation to met effectively manage among membrane and evidences accessed that project based so specific also conditions, including and conditions superpro- constructive, accusability to the arts, and other related conditions, as the property progresses and there is a need to revise the ESC plan, on action plan will be					
PR	OJECT LOC	ATTOM:	PROPERTY DESC	RIPTION:	printer de la consignation de					actionations.			_,				
	r the		Tax Loss		SITE CONDITION	MODELLIN PERGUENCY		SHEET NO. DESCRIPTION ADJ. Breaker and Sediment Control C							initia		
County (County Name Tax May 201-X-XXXXX) Monte, Ordain (Secured in the Sec. 49, 7, 49 S. R.			XX-X-XXXXX		Weekly phan stormagur nmoff, in runnif from mow mail, is occurring	eduding .	FB01 Breaton and Sediment Control Plan PB02 Breaton and Sediment Control Plan		Pendary rest for a septe (TOB): company/Agency:								
"	Morre, Oregon Incated to the Sec. 49, 7, 49 S., R. 46 W.M., County Harry, Oregon			r, c. ou i., r. Marra, Orașon	1. Active parted				Phone:								
I					1	At least once many month, regard whether storoweter runtil is occu-		FBD3 Brosles and Sediment Control D	erio (la	Part							
ATT	TENTION E	723750	15.		3.00	Orași to ecurum that equalor pod as	reference C	FBD4 Broater and Sediment Control D	etails	Description of superin	ere:						
Greg get8	Oregon law requires you to follow rules adopted by the Gregon orbity notification cantur. Those roles are set forth in GAR 852-061-0016 through GAR 852-661-0090. You may obtain				Prior to the site becoming brackly or in anticipation of site inaccessibility.	Once to namen that emission and aretiment control measures are in mortaling control. Any repulsiony material area in repair most be calcie prior to leading the situ.	Sept.	Tan Lots							_		
E po	sub-more review or engine such sub-more values, virus main standard copies of these ratus from the centur by calling \$503-52-7 BRZ. If you have any questions about the variety you may copiest the commer. You many county the conver as hours are during any between commercing an examination. Call \$607-246-46780.			9-252-1987. connect the	leactive periods greaser than four- teer (14) connectative calendar days. A flustede duatur militals the site in	Grice every stones.		Morre County Tex Map			OREGON				4		
bet				meer myd 1690.	 Partocke dupting which the site is immensionable from to inclument remitter. 	If practical, inspections upon occur at a relevant stat accusable discha- point or downstream location.		PREPARED FOR:			OFTRA		JKTA	IION	8		
No.	DATE		REVISIONS	BY	 Purjode dysting sylinch discharge is unaltady don to impair conditions. 	Manthly, Resump mentioning immy open male, or whom sention condi- mates discharges libray.	there	CLEAN WATER SERVICES 2556 SW 1895burn 1896way				PR PR	OJECTT OJECTT OJECTT	TILE			
\Box	09-89-09	Change		MMM	* field a pre-construction greaters of our	and construction recovered that includes the		Hillsborn, OR 97723 Phone: 503-681-5000				rw	HIGHWA	y L			
					All learner than must be remain and section	ant control measures and construction	m Monto.	Flur: 509-681-3029			Dankerer: Norma			iner live			
\vdash				-	happition logs point be found to accord	lead construction previously that forcholds the incomply quality and complyation forch, incomply quality and complyation forch, income with piles. The previously approximate more on acts and made it preliable up response once on acts and made it preliable up response once on acts and made it preliable up response once on acts and made it is present that present (CF at the construction also or at accusive local		, I			Chalgran: Norma		-				
\Box					DEO, agent, or the local aramopality. Di consecutive calender days, retain the E			On. 8472:			EROSION AN	O SEO	WEST.				

Separate sheets for each phase of construction



Verify BMPs shown on phased ESCP are installed and adequate and appropriate for actual site conditions to provide effective functioning

SEDIMENT TRAPS

IF Sediment Trap is provided in location where post-construction water quality basin is proposed, the sediment trap must have 18" of sediment and soil removed AND replaced with material capable of satisfying stormwater management requirements for infiltration and/or water quality treatment

In Addition To evidence or erosion or discharge of sediment the following are enforceable non-compliances:

- BMPs shown on Plans not installed,
- Monitoring not conducted per requirements,
- Monitoring reports not accurate or timely,
- Prohibited discharges not self-reported,
- Corrective action reports not accurate or timely,
- ESCP Not updated (& submitted) to reflect changes on the ground.

DEQ depends of submittals to monitor project compliance – Without submittals, compliance is suspect





"Engineered" Soils

- Subgrade soils stabilized with cementitious material are "engineered soils"
- Where the possibility of runoff exists, from engineered soils, runoff must be captured in correctly sized sediment trap.
- Runoff from engineered soils, captured in sediment trap, must be tested for high pH.
- High pH water must have alkalinity neutralized prior to discharge
- Neutralizing treatments must be approved by DEQ prior to use



Your DEQ Online (YDO)

All Submittals to DEQ Must Be Sent Through the Electronic YDO Portal, including:

- Erosion & Sediment Control Plans (ESCP)
- Environmental Management Plans (EMP)
- ESCP Updates
- Corrective Action Reports
- Payments

(monitoring reports are not periodically submitted, but must be available for DEQ review when asked)

Selected ODOT Staff are YDO "Responsible Officials" with signing authority. ESCMs and others may be delegated YDO Project access as "Consultants", for submittal preparation but do not have signing or submittal authority.

Revise ESCP To Keep it Representative of Current Site Conditions, Including:

When construction plans change, when site conditions change, when BMPs change.

ESCM provides ESCP revisions to Agency W/in 7 days of change, for submittal to DEQ

Agency submits to DEQ within 30 days of revision.

Anticipate additional tasks in schedule & budget

ESCP REVISIONS

Revisions to ESCP will likely be the largest task added to the work of ESCMs




Contractor's ESCM Duties Include:

- Read 1200-CA Permit & keep site permit compliant
- Monitor site as follows:
 - On initial date
 - Every 14 days
 - Within 24 hours of storm events that results in stormwater runoff
 - Within 24 hours of snow melt that results in runoff
- Monitor receiving waters
- Mobilize crews to provide corrective actions
- Fill out monitoring report and submit to Agency (ORS-012-0055: Failing to collect monitoring data required in Schedule B of the permit is a Class 1 [most severe] penalty)



Weather DATA Monitored by DEQ



DEQ oversight of ODOT Projects has grown more strict

Non-Compliance Require Self Reporting & Corrective Actions

- Mistakes happen. Self-Reporting sediment discharge to DEQ actually builds trust,
- DEQ would be suspicious if conditions were always perfect,
- Within 24 hours do the following:
 - Provide narrative of non-compliance,
 - Provide photos of discharge,
 - Clean up sediment or discharge,
 - Provide plans for correcting ESC failure,
- Follow non-compliance report with corrective action.

Non-Compliance Require Immediate Corrective Actions

- Address conditions that caused discharge,
- Clean up sediment contamination left by discharge,
- Complete minor corrective actions by close of next business day,
- Install new or replacement BMPs, required by Corrective actions, within 24 hours,
- If completion of corrective actions within 24 hours is not feasible, document the schedule for implementing the corrective action,
- Revise ESCP to reflect corrective action repairs within 7 days.

Corrective Action Report Include:

- Site name and Project's Permit ID number,
- Description and cause of non-compliance,
- Photos of discharge and NTU of receiving water,
- Period of non-compliance,
- Names of person(s) conducting monitoring,
- Corrective steps taken and timeline of the corrective action,
- Note of weather that may have contributed to the discharge,
- Revisions of ESCP to show corrective action BMPs.

Corrective Action Result:

 When non-compliance is self reported, the discharge cleaned up, the cause of the discharge repaired and a Corrective Action Report submitted, the event will <u>not</u> be considered a permit violation.



EMP requires Appendix A

Appendix A - Environmental
Management Plan Review
Applications for Contaminated Media
Management & Active Chemical
Treatment Systems

February 2022

Includes:

- Contaminated Media Management Plan guidelines,
- Contaminated Media Management Plan Application,
- Active Chemical Treatment Systems guidelines,
- Active Chemical Treatment
 Management Plan Application


WQ Permitting
700 NE Multnomah St
Suite 600
Portland, OR 97232
Phone: 503-229-51:
800-452-40
Fax: 503-229-61

Contact: Blair Edwards

DEQ is a leader in restoring, maintaining and enhancing the quality of Oregon's air, land and water.



Appendix B - Buffer Zone



Permit Requires Additional Tasks

- ESCM has more duties
- Threshold for monitoring after rainfall has changed
- Stricter oversight of concrete wash and alkalinity in stormwater runoff
- Environmental Management Plans (EMP)
- Sheets for each phase of construction
- Buffer Zones
- YDO Electronic Portal required for submittals

ODOT Process Changes

- Revised 00280 Specifications
- Consultant Scope Template Revised
- Erosion Control Manual Revision
- Trainings for designers, Construction
- Scope work for additional tasks in Design & in Construction
- DEQ will require payments through web portal
- Drafting Standards must adapt

Erosion & Sediment Control Plans (ESCP) requirements are more stringent and includes more administrative tasks

DEQ will be more involved in Projects and provide closer scrutiny

ESCM will have more duties and responsibility

ESC installations and maintenance will not be significantly changed from current best practices, but oversight will

Contractors are ODOT's partner in environmental protection and Permit compliance



