

Oregon Department of Environmental Quality

## Oregon Department of Environmental Quality OWQI Basin Summary OWQI Basin Summary

Station	Location Description	Land Use	Water Year Range	OWQI Score	OWQI Status	OWQI Trend		OWQI Trend for	Sub-Index Status and Trend								
						an Magni			т	pН	D	в	тѕ	N	Ρ	Е	
POWDE																	
11494	Burnt R ds Huntington	Range	2014-23	67	Poor	NT						$\downarrow$	↑	↓			
10724	Powder R at HWY 86	Range	2014-23	32	Very Poor	NT			↑	↑				$\rightarrow$			
11490	Powder R at HWY 7 (Baker City)	Range	2014-23	87	Good	NT				↑	↑	↓		→		$\downarrow$	
MALHEU	IR BASIN																
11043	Bully Creek at HWY 20 (Vale)	Agriculture	2014-23	33	Very Poor	NT		<b>.</b>				↓			↑		
11047	Malheur River at HWY 20 (Drewsey)	Agriculture	2014-23	32	Very Poor	↓	-1.1			↑		↓				↓	
10407	Malheur R at HWY 30 (Mouth)	Agriculture	2014-23	22	Very Poor	NT			↑	↑					↑	↑	
11480	Malheur R at Little Valley	Range	2014-23	59	Very Poor	↑	5.6			↑	→				↑	↓	
33266	Willow Creek north of Jamieson, OR	Agriculture	2014-23	36	Very Poor	NT								↑		↓	
10728	Willow Creek at RR Xing east of Vale	Agriculture	2014-23	25	Very Poor	NT							ſ		↑		
OWYHE	EBASIN						-										
36783	Crooked Creek at Kiger Rd	Agriculture	2014-23	77	Poor	NT			↓	t		↓		↑		↑	
11050	Jordan Creek at Arock Rd	Agriculture	2014-23	74	Poor	$\downarrow$	-2.6							$\rightarrow$		↑	
12261	Jordan Creek us of Jordan Valley	Range	2014-23	81	Fair	$\downarrow$	-1.3					↓	↑		↓		
10729	Owyhee R at HWY 201	Agriculture	2014-23	48	Very Poor	NT		╶╻╻╴╴╹╹╹╹╹	↑	↑	↑				↑		
10730	Owyhee R at Rome (Hwy 95)	Range	2014-23	82	Fair	↓	-1.2				$\rightarrow$	↓	↑				