

working for clean rivers

Johnson Creek Oxbow Scour Repair


Ali Young, Project Manager City of Portland Environmental Services September 18, 2019





ENVIRONMENTAL SERVICES CITY OF PORTLAND

NICK FISH, COMMISSIONER MICHAEL JORDAN, DIRECTOR



2012 Aerial




2013 Aerial



2016 Aerial



Cold Water From Outfall







Project Goals

- Stabilize stream bank to protect private property, road, and stormwater outfall
- Create habitat for ESA listed salmon to escape warm water in summer and high flow in winter



December 2016




February 2017

Pre-Construction Sediment Sampling


- Stream sediment samples collected from excavation area
- Analyzed samples for:
 - o Heavy metals
 - o PAHs
 - o PCBS
 - o Phenols

- Pesticides
- o Petroleum
 - Hydrocarbons
- o Phthalates
- All results were below screening level values for benthic
 communities (the bugs fish eat)





Pool Construction





Post-Excavation Sediment Sampling

- Stream sediment samples collected from the excavated area
- Same analytes as pre construction
- All results were below screening level values for benthic communities (the bugs fish eat)





Rootwads





Footer Logs Installed



Installing Rootwads



Rootwads Pinned and Slash Installed









Installing Soil Lifts





Environmental Services | Johnson C

Channel Re-watered








Spring 2019







Environmental Services I Johnson Creek Oxbow Scour Repair



Fish Ladder







Environmental Services I Johnson Creek Oxbow Scour Repair









Errol Creek Confluence and Outfall



Beaver Activity and SE 45th culvert







